

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
PA,
51-PHILA,
591-B-

Kid-Physick House
325 Walnut Street
Philadelphia
Philadelphia County
Pennsylvania

HABS No. PA-1436-B

EXTERIOR PHOTOS: PA-1436 B-1 thru PA-1436 B-3 were taken by Theodore F. Dillon on August 10, 1959.

INTERIOR PHOTOS: PA-1436 B-4 thru PA-1436 B-11 were taken ca. 1958 by Jack E. Boucher. PA-1436 B-12 thru PA-1436 B-20 were taken in December 1959 by an unknown photographer

EXTERIOR PHOTOS

PA-1436 B-1 WEST ELEVATION, FROM NORTHWEST

PA-1436 B-2 NORTH (REAR) ELEVATION (THE NARROW PART WITH OPEN THIRD FLOOR WINDOWS), FROM NORTH

PA-1436 B-3 DETAIL VIEW OF WEST ELEVATION

(For photographs of front elevation of this house, see Kid-Chandler and Kid-Physick Houses, HABS No. PA-1436)

INTERIOR PHOTOS

BEFORE RESTORATION:

PA-1436 B-4 CELLAR, LOOKING SOUTH (TO WALNUT STREET)

PA-1436 B-5 FIRST FLOOR FRONT ROOM. SECOND FLOOR HAS BEEN REMOVED-- NOTE PRESENCE OF SECOND FLOOR WINDOWS (THE LATTER FLOOR WAS REMOVED MANY YEARS AGO), See also PA-1436 B-12

PA-1436 B-6 FIRST FLOOR REAR ROOM. SECOND FLOOR HAS BEEN REMOVED-- NOTE PRESENCE OF SECOND FLOOR WINDOWS AT LEFT. See also PA-1436 B-13

PA-1436 B-7 THIRD FLOOR FRONT AND REAR ROOMS

PA-1436 B-8 FIREPLACE, THIRD FLOOR, SOUTH (FRONT) ROOM, LOOKING WEST. See also PA-1436 B-17

PA-1436 B-9 FIREPLACE, ATTIC, SOUTH (FRONT) ROOM, WEST WALL. See also PA-1436 B-18

PA-1436 B-10 DOOR LATCH, ATTIC

PA-1436 B-11 DOOR LATCH, ATTIC

(continued on page two)

DURING RESTORATION:

- PA-1436 B-12 FIRST FLOOR FRONT ROOM. SECOND FLOOR HAS BEEN REMOVED-- NOTE PRESENCE OF SECOND FLOOR WINDOWS. See also PA-1436 B-5
- PA-1436 B-13 FIRST FLOOR REAR ROOM. SECONO FLOOR HAS BEEN REMOVED-- NOTE PRESENCE OF SECOND FLOOR WINDOWS AT LEFT. See also PA-1436 B-6
- PA-1436 B-14 THIRD FLOOR SOUTH (FRONT) ROOM, LOOKING NORTH
- PA-1436 B-15 WINDOW, THIRD FLOOR NORTH (REAR) ROOM, LOOKING NORTH
- PA-1436 B-16 FIREPLACE, THIRD FLOOR, NORTH (REAR) ROOM, LOOKING NORTHWEST
- PA-1436 B-17 FIREPLACE, THIRD FLOOR, SOUTH (FRONT) ROOM, LOOKING WEST. See also PA-1436 B-8 in pre-restoration condition
- PA-1436 B-18 FIREPLACE, ATTIC, SOUTH (FRONT) ROOM, WEST WALL. See also PA-1436 B-9 in pre-restoration condition
- PA-1436 B-19 ATTIC ROOM
- PA-1436 B-20 FIREPLACE. FLOOR DESIGNATION NOT KNOWN